FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7712 AND SIGNED WHEN RETURNED

2 2 . /	7
DATE INSPECTED 3-30-6	I IF SO HOW AND LOCATION FROM WYE 19 W. of UPSTREAMM
HOUSE NO 108	FIRST MANHOLE DESCRIPTION STREAM NO 7 - 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
110882 NO.	— DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 6	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	and the second of the second o
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
	TERAL TO WALL OF BUILDING SERVED.
	A'
	- mountain and the state of the
ALM SHEET SHEET AND A TO SELECT A TO SELECT AND A SECOND STATE OF THE SECOND SHEET AND A	months with the windpayer of the second of t
	A CONTRACTOR OF THE PROPERTY AND
N	gar. R
<i>T</i> *	18 X 18 X
· · · · · · · · · · · · · · · · · · ·	P 101
SIGNED W. HAMME	FILED AT ENGINEER'S OFF CE'
INSPECTOR FOR C	CITY
いってリノノート	The state of the s

N° 7712 '

OF THE DEPARTMENT OF PUBLIC SERVICE.

PERMIT TO TAP SEWER

	Massillon,	OHIO, H/Marches 10 .
RECEIVED OF	A Com	FEE OF \$500000
	<u> </u>	
TO TAP 9 1 9 1 9 1 9 1 9 1 9 1 9 1 9 1 9 1 9	SEWER ON THE	<u> </u>
of	AVE. ST. TYPE OF STREET	dard he face
THE PREMISES BEING LOT NO.		

NAME OF CONTRACTOR TO THE TOTAL CO.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.