

Nº 7718

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-1-64

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1203


SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 104' SOUTH OF H 8'DEEP
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7718

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

March 30 1911

RECEIVED OF

Harry Urban

FEE OF \$

5⁰⁰

FOR WHICH PERMISSION IS GRANTED

Carl Oser

TO TAP

Dan

SEWER ON THE

West

OF

14th St. S.W.

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

8944

HOUSE NO.

1203

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Urban

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.