

✓
Nº 7720

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-1-64

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1113

SIZE OF PIPE USED 6"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

W. HAMMEIR
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

✓
Nº 7720 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 1,

RECEIVED OF Dale Rogers

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED James Tortora

TO TAP San

SEWER ON THE South

OF 2nd N.E.

AVE.
ST. TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 12293

HOUSE NO. 1113

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Dale Rogers

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**