

✓
No 7723

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-10-69

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 734

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 125' N. OF H/ 7' DEEP


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR STEINBACH

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N 



SIGNED

R. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

✓
No 7723 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO

April 9

RECEIVED OF

Ind Steinbach Excavating

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Tap Sewer

TO TAP

San
Woodview

SEWER ON THE

East

OF

AVE.
ST. TYPE OF STREET

Dirt

THE PREMISES BEING LOT NO.

23-1185

HOUSE NO.

734

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ind Steinbach

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.