

Nº 7745

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-3-44

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

AT MH 7" DEEP

HOUSE NO. \_\_\_\_\_

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R G MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS \_\_\_\_\_

✓  
✓  
Nº 7745

OFFICE OF THE DIRECTOR OF PUBLIC SE  
PERMIT TO TAP SEWER

MASSILLON, OHIO.

RECEIVED OF

*R. G. Marks*

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED

*Board of Education*

TO TAP

*Sanitary*

SEWER ON THE

*West*

OF

*3rd N.W.?*

AVE.

ST. TYPE OF STREET

*Black Top*

THE PREMISES BEING LOT NO.

*OL-207*

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*R. G. Marks*

Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.