

✓  
Nº 7751

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-28-69

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM ?

HOUSE NO. 211

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH ?

WAS LATERAL AT CURB? IN PROP YES


WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR REMLEY & GRIFFIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N →

TREMONT



SIGNED

Roy Latham  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

✓  
N<sup>o</sup> 7751

OFFICE OF THE DIRECTOR OF PUBLIC SE  
PERMIT TO TAP SEWER

MASSILLON, OHIO

RECEIVED OF

*Aug. 27*  
*Cohen Oil Co.*

FEE OF \$

*5.*

FOR WHICH PERMISSION IS GRANTED

TO TAP

*Sani*

SEWER ON THE

*South*

OF

*Dumont St*

*- 5*  
AVE.

ST. TYPE OF STREET

*Hardwood*

THE PREMISES BEING LOT NO.

*5844*

HOUSE NO.

*311*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Ray Kewley*

Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.