## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7766 AND SIGNED WHEN RETURNED

DATE INSPECTED 11-24-64	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2537		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 211 W. 55 M	6'DEER
WAS LATERAL AT CURB? VES		
WAS ATTACHED TO MAIN No	NAME OF CONTRACTOR DIANA \$	R. LIND:
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
mana na minana na mana na minana na mina Tanàna manana manan		18"
		1 7 pp
	e Storic e e entrantemo porte	32
$\bigvee$		L5' K 6 DP.
SIGNED Roy Lethan	FILED AT ENGINEER'S OFFICE	->
UNSPECTOR FOR CIT		1
REMARKS		

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

MASSILLON, OHIO LOV. 23
RECEIVED OF January FEE OF \$50  FOR WHICH PERMISSION IS GRANTED A. D. Land
FOR WHICH PERMISSION IS GRANTED A. D. Decena
TO TAP Secretary SEWER ON THE South
of Wilson ave S.E. AVE. TYPE OF STREET Hard Jurlace
THE PREMISES BEING LOT NO. $6952$ HOUSE NO. $3537$
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.