

Nº 7769

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-14-64

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 932

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 2

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR MR. R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

No card
new card
no photo
repaired

R. Clag

No 7769

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO

Dec. 7,

RECEIVED OF

Homer Schneider

FEE OF \$

5⁰⁰

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

North

OF

Hatch, N.E.

AVE.

ST. TYPE OF STREET

Hardwick

THE PREMISES BEING LOT NO.

3986

HOUSE NO.

942

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Rindley

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.