

Nº 7771

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-9-69

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 720

SIZE OF PIPE USED 6" CAST IRON  
DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT PROP. LINE  
CURB YES

OLD TO HOUSE


WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR \_\_\_\_\_

D & A PLUMBING

R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED \_\_\_\_\_

Roy Latham  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

Nº 7771

OFFICE OF THE DIRECTOR OF PUBLIC SE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, Dec. 7,

RECEIVED OF

Martin Oil Co.

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

East

SEWER ON THE

East

OF

Lincoln Way, East

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

477-A

HOUSE NO.

720

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Penley

Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.