

Nº 7776

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

NO WORK DONE ON OUTSIDE

SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7776

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Feb. 15,

RECEIVED OF John P. Vallier

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Sanitary

TO TAP Lincoln Hwy

SEWER ON THE North

OF Lincoln Hwy

AVE.

ST. TYPE OF STREET Washington

THE PREMISES BEING LOT NO. _____

HOUSE NO. 3206

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR John P. Vallier

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**