


✓ 7-

Nº 7778

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-27-65 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 425
SIZE OF PIPE USED 6" UP DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 19' S. 05' UPSTREAM MH 7
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN No NAME OF CONTRACTOR R. MARKS
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. Latham INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7778

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 5

RECEIVED OF Donald Kandle

FEE OF \$ 5⁰⁰

FOR WHICH PERMISSION IS GRANTED R. S. Marks

TO TAP Sanitary

SEWER ON THE West

OF 23rd W. B.

AVE.
ST. TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 7361

HOUSE NO. 425

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. S. Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.