

7-1

Nº 7780

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-15-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 923

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


7' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR A. DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

R. L. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7780

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 9

RECEIVED OF John Martin

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary

SEWER ON THE West

OF 9th - Sec

AVE.

ST. TYPE OF STREET North Jackson

THE PREMISES BEING LOT NO. 11306

HOUSE NO. 933

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR ~~Elmer Jones~~ A. J. DIANA

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.