

Nº 7782

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-16-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2115

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

182' N. 05 M @ SHERI 8' D₁₂



WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

A. DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Ray Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7782

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/15

RECEIVED OF Robert Charles

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary

SEWER ON THE 3rd

OF Glendon St

AVE.

ST. TYPE OF STREET Highway

THE PREMISES BEING LOT NO. 11357

HOUSE NO. 2115

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. C. Brown

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.