

✓ 17 =

Nº 7796

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 5-18-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1978189

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

22' E, 05174 7 0.


WAS LATERAL AT GURB? Prop YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Ray Hathorn
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7796

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 17

RECEIVED OF Geo. Hammer

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary

SEWER ON THE South

OF Mcadden No

AVE.

ST. TYPE OF STREET Chgo & Lead

THE PREMISES BEING LOT NO. 11769

HOUSE NO. 187 + 189

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. S. Sparks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.