FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7798 AND SIGNED WHEN RETURNED

DATE INSPECTED 5-21-65	IF 50 HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED NONG	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 8 0/17/7	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATER		300
	and the second of the second o	4 9 9 8

SIGNED Roy Latham	ST# ST. N.E.	20
INSPECTOR FOR CITY	to Bear the growing the leading the light for a theory	:

Relay

office of the director of public services of the director of the dire

	MASSILLON, OHIO,		
RECEIVED OF	Dischel		FEE OF S
FOR WHICH PERMISSION IS GRANTED	-		
Sanctury		All. Z	·
TO TAP OF TOTAP OF TOTAP TOTAP TOTAP	AVE. ST. TYPE OF STREET	Hard.	unfare
THE PREMISES BEING LOT NO.			yer mark
WORK TO BE DONE IN ACCORDANCE WITH O	RDINANCE No. 2323,	DULY PASSED B	Y THE CITY COUNCIL, AN
	r De grande gr	·	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.