

✓
17-

Nº 7809

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-19-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 568

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N 



SIGNED

R. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7809

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 12
RECEIVED OF Carl Case FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary SEWER ON THE East
OF 25th N.W. AVE. ST. TYPE OF STREET Dirt
THE PREMISES BEING LOT NO. 7105 & 7106 HOUSE NO. 568

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry Urban

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**