Nº 7812

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-23-65 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2030 DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 6" DOWN STREAM TO DITCH AT 235 E. OF M 8 DEED
WAS LATERAL AT SURE? VES POP Propling NO NAME OF CONTRACTOR H Malan
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
N
\$ 30° 80 NO 8' OP.
30 g br 18'
SIGNED R. Walter FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY
REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SEI

Nº 7812

		MASSILLON, OHIO, June 16		
. 1	RECEIVED OF	Tichan	L Dung	FEE OF \$
FOR WH		Jantan		<u> </u>
TO TAP	1,	110	SEWER ON THE	- Jarch
OF	<u>Stro</u>		AVE. ST. TYPE OF STREET	1025 3048
THE PRE	(12) - (12)	2472 /3 LOT NO	37817472 H	DUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry Mibau

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.