

Nº 7815

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-23-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE: DOWN STREAM 38' S. of M 13' D/E
UP

HOUSE NO. 322


SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR G. Seaton

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. Kallie
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7815

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

June 22

RECEIVED OF

Geo Sedon

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

Lead line

TO TAP

Sanitary

SEWER ON THE

Left

OF

322 Arthur S. E.

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

12371 - 372

HOUSE NO.

322 - Arthur
Between lot

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo Sedon

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.