

✓ 6-1
Nº 7819

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-2-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1651

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 78' N. OF MH
CURB LINE AND DEPTH 9' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR BEAVER EXCA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7819

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

RECEIVED OF

Beaver Excavating

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

Harold Burnier

TO TAP

Sanitary

SEWER ON THE

OF

10th St. N.E.

AVE.

ST. TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

8472-13

HOUSE NO.

1651

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beaver Exc.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.