

✓ 4-

Nº 7822

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-7-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 9' W. OF UPSTREAM
UP

HOUSE NO. 825


SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR A. DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED W. HAMMER INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7822

OFFICE OF THE DIRECTOR OF PUBLIC SE.
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 8

RECEIVED OF A. J. Drana

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Clyde Luke

TO TAP Sanitary

SEWER ON THE South

OF Westmore

AVE.

ST. TYPE OF STREET Det 7

THE PREMISES BEING LOT NO. 9398

HOUSE NO. 825

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Drana

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**