

✓ 18-6

Nº 7826

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-21-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM WYE 1
81' E. 05 M' ON TAMMI

HOUSE NO. 2039

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR H. URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑
H

MANHOLE



SIGNED

R. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7826

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/22

RECEIVED OF

Avery Carlson

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

East

OF

Hubert Rd. W

AVE.
ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

Port Lot - 12077

HOUSE NO.

2034

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Urban

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.