

✓6

Nº 7833

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-18-65 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 730

SIZE OF PIPE USED 6" UP DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 18' S. OF UP STREAM M.
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. HALTER INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7833

OFFICE OF THE DIRECTOR OF PUBLIC SE.
PERMIT TO TAP SEWER

MASSILLON, OHIO, August 18

RECEIVED OF Massillon Boys Club FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED R. G. Marks

TO TAP Sanitary SEWER ON THE East

OF Duncan SW AVE. ST. TYPE OF STREET Black-top

THE PREMISES BEING LOT NO. pt 04-132 HOUSE NO. 730

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. G. Marks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**