FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7843 AND SIGNED WHEN RETURNED

DATE INSPECTED 9-27-65 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1/34 SIZE OF PIPE USED 6" WAS LATERAL AT GURB? YES WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR G. MALEVITE
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
16' A R 1' O R 1
No opens
SIGNED POLITICATE FILED AT ENGINEER'S OFFICE 13-22-65
REMARKS

Nº 7843

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	
\sim \sim \sim \sim \sim	3	
Howard Q	Simete FFF OF	50
RECEIVED OF	FEE OF	s
FOR WHICH PERMISSION IS GRANTED		
1		
of Scand NE AVE.	/ER ON THE	
TO TAPSEV	/ER ON THE	
Some of soft and the second	the state of the s	
OFST. TYP	E OF STREET	
		- 1
THE PREMISES BEING LOT NO. 12300	, HOUSE NO	
THE PREMISES BEING LOT NO.	· · · ·	
	<u>n kin ana un</u>	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	NO. 2323, DULY PASSED BY THE CITY COU	NCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.		-
	DALEVI	10
Second Second	and the second	
NAME OF CONTRACTOR	- Jan Marie	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.