



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 7864 AND SIGNED WHEN RETURNED

DATE INSPECTED 11-19-65 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 427
SIZE OF PIPE USED 4" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO
WAS ATTACHED TO MAIN REPAIRED IN ST. NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

USED 45° BEND
1-2' STRAIGHT PIPE



SIGNED L. N. Katten FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY

REMARKS REPAIRED PIPE ON STACK PAID BY CITY

OFFICE OF THE DIRECTOR OF PUBLIC SEWER
PERMIT TO TAP SEWER

Nº 7864

REPAIR

MASSILLON, OHIO.

11/16/65

RECEIVED OF

Warren Mendelsohn

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sand.

SEWER ON THE

West

OF

6th St. S.W., -

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

1856

HOUSE NO.

427

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. G. Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.