Nº 7874

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-25-	The state of the s
· · · · · · · · · · · · · · · · · · ·	FIRST MANHOLE DOWN STREAM
HOUSE NO. 753	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CREED LINE AND DEPTH S 1 0 5 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
WAS LATERAL AT GURB?	Same Properties of the first of the material state of the party of the
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR G. Corpos
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.
age and the second of the second property of the second of	1/0',
	1 N
	or to a tot skipping the utilization or assistance of the contract of the cont
en e	
	$e \leftarrow s' \rightarrow$
SIGNED TOY KAR	FILED AT ENGINEER'S OFFICE
INSPECTOR	
REMARKS	

Nº 7874

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

Massillon, Ohio	Feb. 9.
RECEIVED OF Oakes Conch. Inc.	FEE OF \$!
FOR WHICH PERMISSION IS GRANTED Cakes Cant.	Live:
TO TAP Sanitary SEWER ON THE	West
of Bittersmeet Un. 71- E AVE. TYPE OF STREET C	hip & Seal
THE PREMISES BEING LOT NO. 12466 HOUSE N	75.3
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASS	
OF THE DEPARTMENT OF PUBLIC SERVICE.	
010 110	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.