

RELAY

✓ 1-9

No. 7877

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-9-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

REPAIR

HOUSE NO. 16

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N



SIGNED

A. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

BUILDING

REMARKS

Nº 7877

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO

March 10

RECEIVED OF

James Capano

FEE OF \$

5.⁴

FOR WHICH PERMISSION IS GRANTED

Ray Remley

TO TAP

Sanitary

SEWER ON THE

North

OF

Penn Ave.

AVE.
ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

2284

HOUSE NO.

16

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Remley

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.