

✓ 2-9

Nº 7881

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-25-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 419

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No



Repaired in yard

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*REPLACED BROKEN
4" PIPE UNDER
STACK OR CLEAN OUT
AS PER
PLAN*



SIGNED *N. Latham*
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7881

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

Repair

MASSILLON, OHIO March 24

RECEIVED OF Joe Vaughn FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED Ray Remley OWNER

TO TAP Sanitary SEWER ON THE South West

OF 5th St. S. W. AVE. ST. TYPE OF STREET Chip & Seal

THE PREMISES BEING LOT NO. 1740 HOUSE NO. 419-5th

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray Remley

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.