

Nº 7882

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-29-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2012

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

REPAIRED IN YARD

WAS ATTACHED TO MAIN No



NAME OF CONTRACTOR

R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



ROOTS IN LINE



SIGNED L. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

Nº 7882

RELAY OF
REPAIR

MASSILLON, OHIO, March 29

RECEIVED OF Raymond Remy FEE OF \$ 5-

FOR WHICH PERMISSION IS GRANTED Mrs. Johnson

TO TAP Sanitary SEWER ON THE North

OF Lincoln Way, W AVE. ST. TYPE OF STREET Hard Surface

THE PREMISES BEING LOT NO. 06.168 HOUSE NO. 2012

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remy

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.