## Nº 7908 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 7908	AND SIGNED WHEN RETURNED	
DATE INSPECTED 9/4/66	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	ing the state of t	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
	ATERAL TO WALL OF BUILDING SERVED.	
eren eren eren er	SEE INSPECTER FAILD 1800,	¢ 22.
	en de la Carlo de Carlo de La Lacia de Carlo de Maria de Maria de Maria de Carlo de Carlo de Carlo de Carlo de La composição de Carlo de Car	
		9
SIGNEDINSPECTOR FOR	FILED AT ENGINEER'S OFFICE	
REMARKS		

## Nº 7908

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

July 3
Massillon, Ohio,
BECEIVED OF Beaning Theresting FEE OF S. J.
RECEIVED OF FEE OF \$
FOR WHICH PERMISSION IS GRANTED 1-711 art
TO TAP Samuray SEWER ON THE That
OF 27 14 77. E. AVE. TYPE OF STREET
THE PREMISES BEING LOT NO. P. D. h. 417 HOUSE NO. K- Mart DE
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.
Benn
NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.