

V 6-1
N^o 7910

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-8-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1811

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 21' N. OF MH 7' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED J. N. Graham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7910

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 8
RECEIVED OF Paul Gutzan FEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED Paul Gutzan
TO TAP Sanitary SEWER ON THE West
OF 11th St. V 716 AVE. ST. TYPE OF STREET Hard surface
THE PREMISES BEING LOT NO. 8428 & 8429 HOUSE NO. 1811

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Hoban

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.