FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

2 AP	
DATE INSPECTED	IF SO HOW AND LOCATION FROM TAPPED MAY 8 DEED
HOUSE NO. 188-90	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
 WAS LATERAL AT CURB? NO	A Company of the Company of American Company of the
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR WAUTAT
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	N 12 DEE
	T 45 ORIEND
	26'
A	The second secon
J. Thank	& D P1
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 7914

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MAS	SILLON, OHIO July 15
Wantat Cones	to Charles 5
RECEIVED OF	
	W audit
Sometant I	Horth
711-Cadalin AVE.	Margar Har Oran
11959	HOUSE NO. 189-190
THE PREMISES BEING LOT NO.	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME DE CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.