## Nº 7923 AND SIGNED WHEN RETURNED

	DATE INSPECTED 9-23-66 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
	HOUSE NO 529	
	SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE CONTROL OF THE CURB LINE AND DEPTH	
	WAS LATERAL AT CURB? VES	
¢'	WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR PARTY MANTE	
	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
er construction	the company of the co	
्या होते. कृतिकृति <b>स</b> ्	ASSESSED AND ARE NOT ALL AND THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY SHOWS SHOW SHOWS AND	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	D
)		
turu tu witu	1 Lathern	
	SIGNED INSPECTOR FOR CITY	_

## Nº 7923

## PERMIT TO TAP SEWER

R. L. O. L. H.	MASSILLON, OHIO Tergest 3/
RECEIVED OF ANALYSIS FAI	FEE OF \$
	a Kendrick
TO TAP Secretary s	EWER ON THE South
OF Jest 71. E. AVE. ST. T	YPE OF STREET HERE
•	64 HOUSE NO. 539
WORK TO BE DONE IN ACCORDANCE WITH ORDINAL	ICE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN

NAME OF CONTRACTOR LUdy Hartmann

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.