

✓ 1-

Nº 7925

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-24-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 616

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Prop YES

Repair


WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR _____

R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
F



SIDEWALK

SIGNED _____

W. HAMMER
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Reboy

Nº 7925

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, September 12 191

RECEIVED OF Haldubrum

FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED Fritz Keller

TO TAP Sanitary

SEWER ON THE North

OF Lincoln St. S.W.

AVE.
ST. TYPE OF STREET

Head Surface

THE PREMISES BEING LOT NO. 9322 9321

HOUSE NO. 616 612

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Haldubrum

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.

9321 - 612
3927 - 614
616