

✓

Nº 7936

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-12-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1007

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL ~~AT CURB~~ ^{IN-PAV} YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR R G MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7936

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, October 12

RECEIVED OF

R. B. Marks

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

Garman Bell

TO TAP

Sanitary

SEWER ON THE

South

OF

Anderson Ave. N.E.

AVE.

ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

2839

HOUSE NO.

1007

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Marks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**