## No. 7937 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-17-66 IF SO HOW AND LOCATION FROM TAPPIED 177 5.05 My 11/4
HOUSE NO. 633 \$ 635
SIZE OF PIPE USED CURB LINE AND DEPTH
WAS LATERAL AT CURB? No
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR TO LERAN
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
3'0
12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
177'
SIGNED FILED AT ENGINEER'S OFFICE
REMARKS

## Nº 7937

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

•		Massillo	4, OHIO, PREATHER	17
RECEIVED OF	Harry	Wahan.		
FOR WHICH PERMISSION	$\mathcal{O}_{-}$	Hand		
TO TAB OF CLIPTIC	Trust	SEWER ON THE	_ Chet	
344	40 W	AVE.	- Dent	
THE PREMISES BEING L	OT NO. P.L.C	12919 1.4.399	, HOUSE NO. 6 3 3	\$ 635
WORK TO BE DONE IN A	CCORDANCE WITH	H ORDINANCE No. 2323,		

NAME OF CONTRACTOR HAMY Makes

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.