

✓ 7-

THE FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 7943

DATE INSPECTED 11-5-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1219

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 182' W OF MH 6' DEEP
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7943

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, November 1

RECEIVED OF Racee Marks FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED Massillon Baptist Temple

TO TAP Sanitary SEWER ON THE Sanitary

OF Overlook Ave. S.W. AVE. ST. TYPE OF STREET chip & seal

THE PREMISES BEING LOT NO. O. L. 288 HOUSE NO. 1219

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.