

✓ 1-

ATTACH TO REPORT TO INSPECTOR
NO. 7945 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____ IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____ FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY

REMARKS _____

Nº 7945

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO

RECEIVED OF

Beamer & Transiting

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

West

OF

Grand Rd., N.E.

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

5476

HOUSE NO.

811

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beamer

*Installed without
Inspection
(Repair)*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.