

✓
3.

Nº 7956

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-9-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 726

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 10' EAST OF MH 7 1/2' DEEP.
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR A. DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7956

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Jan 6,

RECEIVED OF

Jacob Glick

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Tap into

TO TAP San.

SEWER ON THE North

OF Sheffield

NE.

AVE.

ST. TYPE OF STREET Chipp & Seal

THE PREMISES BEING LOT NO. 3934

HOUSE NO. 726

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR AJ Diana
Jacob Glick

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**