FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7960 AND SIGNED WHEN RETURNED

HOUSE NO.) 1 1 6 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 154' SOUTH MY 8'DEED WAS LATERAL AT CURB7 VES
SIZE OF PIPE USED 6" DOWN STREAM TO DITCH AT 154' SOUTH MY 8'DEEP WAS LATERAL AT CURBI VES
The state of the s
NAC ATTACHED TO MAIN
WAS ATTACHED TO MAIN NAME OF CONTRACTOR
<u>and and a constant of the constant in the constant of the con</u>
Carried Will the manager of the specific and the control of the state
The BENG
27')
S.DEEP
91 0 154'
SIGNED FILEDAT ENGINEER'S OFFICE

\mathbf{N} ? 7960

PERMIT TO TAP SEWER

		Massillon	1, OHIO, MARCH 13
RECEIVED OF_	GLICK	E WESVER	
FOR WHICH PERMISSIO	N IS GRANTED.	A.J. DIAIRA	
		·	13 KL ST. S. CU, EAST
			. Ga Come Strac
THE PREMISES BEING L	от NO, <u>888</u>	3, PT. 8162	_, HOUSE NO
WORK TO BE DONE IN A		•	DULY PASSED BY THE CITY COUNCIL, AN

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.