1.2 ville 10, 1.5 ville 10 per Following data to be answered by inspector and signed when returned

DATE INSPECTED 4-3-67	IF SO HOW AND LOCATION FROM IN DISAC END MIGHED	wiw
HOUSE NO. 920	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
SIZE OF PIPE USED	CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No	A CONTRACT OF THE CONTRACT OF A CONTRACT OF	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR PARKS	
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
	M M M M M M M M M M M M M M M M M M M	مراثة مؤاهمه
No. 1 Section ## Section in the Sect		86
SIGNED Lattern	FILED-AT ENGINEER'S OFFICE	
REMARKS	The state of the s	

Nº 7961

PERMIT TO TAP SEWER

RECEIVED	or	re Marks. Friendsky Ba	eact CA	fee of \$_ (no.es)
TAP	SSION IS GRANTED.	SEWER ON THE	J. O.	and the second
3 =	M. J. E.	AVE. ST. TYPE OF STREET	Chips	# deal
IE PREMISES BEIJ	NG LOT NO.	42,143 \$ 144		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.