

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 7975

DATE INSPECTED 5-26-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1606


SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 34' WEST OF MANHOLE ON OXFORD 10' DE

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR MALEKITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7975

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO

May 25

RECEIVED OF

Robert Heston

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

Robert Heston

TO TAP

Sanitary

SEWER ON THE

East

OF

Hendee Rd. N.E.

AVE.

ST. TYPE OF STREET

Clay & Steel

THE PREMISES BEING LOT NO.

8504 & 8503

HOUSE NO.

1606

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malanite

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.