

182

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 5-31-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 759

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 72' NORTH OF M 10' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR THOMPSON

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7976

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 26

RECEIVED OF

Robert Thompson

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED

William Craybill

TO TAP

Sanitary

SEWER ON THE

West

OF

Lockport Ave. N.E.

AVE.

ST. TYPE OF STREET

City & Sub

THE PREMISES BEING LOT NO.

12504

HOUSE NO.

759

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Thompson Lumber Co.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.