

51

No. 7978

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-2-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 745

SIZE OF PIPE USED 6-2-67

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


291' SOUTH OF M 7' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR HARRBAUGH

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7978

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO May 29

RECEIVED OF Carl Orr FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED Carl Orr

TO TAP Sanitary SEWER ON THE West

OF 19th V H-E AVE. TYPE OF STREET chip & Seal

THE PREMISES BEING LOT NO. 7950-7951 HOUSE NO. 745

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Hatchough

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.