

✓
3-1:

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 7985 **AND SIGNED WHEN RETURNED**

DATE INSPECTED 7-15-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

STUB IN MT 11' DEEP

HOUSE NO. 708-12 Harmon

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


SIZE OF PIPE USED 12"

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR A DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7985

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 3
RECEIVED OF Waltering Ripert FEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED Waltering Ripert
TO TAP Sanitary SEWER ON THE N. V. East
OF Harmon Place W.E. AVE. TYPE OF STREET Chap & Seal
THE PREMISES BEING LOT NO. Pt. 1389 HOUSE NO. 708-712 Harmon

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR G. J. Liars

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.