

17-13 ✓

2

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-17-67 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 584

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 25' S. OF 14' 3" D

WAS LATERAL AT PROP YES

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR E.C. VOLT

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY

REMARKS _____

Nº 7989

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO

RECEIVED OF

FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.