


SIGNAL BUILDING
RELOCATION OF 6" SAN.
SEWER

No 7993



12-28-74
HOLDER BAUM DRAIN

1-13 ✓

No. 7993

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-21-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 54

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. S. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

1967
Nº 7993

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 3

RECEIVED OF

Parce Marks

FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED

City - Fire - Police License

TO TAP

Sanitary

SEWER ON THE

North

OF

Charles Ave. S.E.

AVE.
ST. TYPE OF STREET

Chip & L

THE PREMISES BEING LOT NO.

1130

HOUSE NO.

5 - City 1/2

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.