## No. 7998 AND SIGNED WHEN RETURNED

em transfer in the second of t	SO HOW AND LOCATION FROM RST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF SIRE LICED 6 // DO	STANCE FROM FIRST MANHOLE - Server OWN STREAM TO DITCH AT IRB LINE AND DEPTH	9 DE
WAS LATERAL AT CLIRB? VIES  WAS ATTACHED TO MAIN NO NO	AME OF CONTRACTOR	•
SHOW BY DIAGRAM RELATION OF LATERAL		<del></del>
	4' 6'p	_
t suutivas vastelija kasa ja katelea valtavat pavat ja ja valta ja	A CONTROL OF A CON	
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE	
	for the state of a life of the discould be	

## Nº 7998

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO
RECEIVED OF	- Bartle
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED.	POYER
TO TAP. SE	WED ON THE PARTY.
TO TAP	WER ON THE
OF AVE. TY	PE OF STREET
THE PREMISES BEING LOT NO.	HOUSE NO.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	e No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	
NAME OF CONTRACTOR	The second secon

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.