



7-20

Nº 8000

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-4-67IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 824-26SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 78' N. 05° 41' @ OVERLOOKSWAS LATERAL AT CURB? YESWAS ATTACHED TO MAIN NONAME OF CONTRACTOR D. HAMEL

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED N. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

N^o 8000

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, August 29 1918

RECEIVED OF George Putnam FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary SEWER ON THE East
OF 14th S.W. AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 4730, HOUSE NO. 824-826

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.