

✓
Nº 8011

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-26-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 941

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? —

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William H. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 8011

PERMIT TO TAP SEWER

MASSILLON, OHIO,

October 25

RECEIVED OF

Haldubaum

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

William Crane

TO TAP

Sanitary (Latrine)

SEWER ON THE

South

OF

S.W. 1/4 - North of Main

AVE.

ST. TYPE OF STREET

Gravel

THE PREMISES BEING LOT NO.

1920

HOUSE NO.

941

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haldubaum

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.