

✓ 9:41

Nº 8019

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-13-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 308

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 2' N. of M 5' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED L. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS Relay Retained 10' of pipe

RECEIVED 12-13-1913

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 8019

PERMIT TO TAP SEWER

Relay

MASSILLON, OHIO,

12-13-1913

RECEIVED OF

St. L. Markes

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED

St. L. Markes

TO TAP

Sanitary

SEWER ON THE

East

OF

15th St. N.E.

AVE.

ST. TYPE OF STREET

Wood Street

THE PREMISES BEING LOT NO.

628

HOUSE NO.

308

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

St. L. Markes

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.